

## ATODIAD A

Rhan o'r adeilad	Argymhelliad
Tu allan i'r adeilad	Blaen pob gris i fod yn llachar
	Canllawiau lle mae dwy neu fwy o risiau
Parcio Anabl	Creu o leiaf dri man parcio sy'n cydymffurfio'n llwyr ac sydd mor wastad â phosibl.
Mynedfeydd Adeiladau	Arwyddion allanfa uwchben y drysau allan diwethaf
Coridorau a Llwybrau	Arwyddion gwell ar allanfeydd
Adnoddau Toiledau Anabl	Sicrhau fod y cortyn argyfwng o fewn cyrraedd wrth eistedd ar y toiled ac o'r llawr
Mynedfa Adeilad Siambr y Cyngor	Golau cryfach neu sicrhau fod y golau presennol ymlaen yn ystod oriau swyddfa.
	Mae'r mat tywydd allanol o ddeunydd cnau goco, ystyried newid am fatiau eraill craidd isel ond dim ond wrth adnewyddu
Llawr Gwaelod Siambr y Cyngor	Gosod rheiliau llaw o boptu'r grisiau at y man uwch lle mae'r cyhoedd yn eistedd
	Gosod breichiau ar y seddau i helpu'r rhai sy'n cael trafferth i godi. Sicrhau fod yna gymysgedd o seddau yn cynnig y cymorth hwn.
	Ymchwilio i ddarparu lle i gadeiriau olwyn i'r cyhoedd ar lefel hygyrch, gallai hyn fod yn rhywle ar y lefel hon ond, o ddewis, mor agos â phosibl at fan gwastad wrth ddod i mewn a gadael. Creu o leiaf ddau le gyda seddi arferol ar gyfer gofalwyr os bydd angen
	Ymchwilio i'r posibilrwydd o osod ramp yn lle'r ddwy ris sy'n arwain i lawr at lefel isaf y siambr. Byddai hyn yn agor lefel ychwanegol cyfan at ddefnydd rhai mewn cadair pe bai angen.
Grisiau	Gosod arwyddion cyfeirio clir ar bob gris yn arwain at yr allanfeydd terfynol.
Adnoddau Toiledau Anabl	Canfuwyd fod y canllawiau braidd yn uchel i ddefnyddwyr cadeiriau olwyn ac nad oedd fawr o le i allu gafael. Ystyried newd y canllaw ochr chwith ar i lawr am un hirgrwn neu grwn a ddim uwch na 750mm o'r llawr. Ni fyddai'n rhesymol gosod canllaw newydd ar yr ochr dde.
Coridorau a Llwybrau llawr cyntaf bloc J	Gosod canllaw, hirgrwn neu grwn, ar yr ochr chwith wrth fynd i lawr ar uchder o 750mm i helpu defnyddwyr cadeiriau olwyn a'r rhai sy'n cael trafferth cerdded.

## APPENDIX A

1	Part of building	Recommendation
2	Building approach	All step nosings to be highlighted
3		Handrails should be included on all steps of two or more risers
4	Disabled Parking	create a minimum of three fully compliant disabled bays in areas that are as level as possible.
5	Building Entrances	Exit signage is located above final exit doors
6	Corridors and Passageways	Improve exit signage
7	Disabled WC Facilities	Ensuring that the emergency pull cord is reachable from both the WC seated position and floor area
8	Council Chambers Building Entrance	Increase lighting or ensure that current lighting is switched on during office hours
9		External weather matting is of a coconut material, consider replacing with alternative low core matting only if renewing.
10	Ground Floor Council Chambers	Placing handrails offering support on steps either side of the raised public seating area
11		Seating is accompanied with arms to assist those that may have difficulty rising. Ensure that a mixture of chairs offer this support
12		Investigate providing wheelchair space for public members on the accessible level, these can be located anywhere on this level but preferably nearest to a level entry/exit point. Create a minimum of two spaces with standard seating nearby for carers if needed.
13		Investigate replacing the two steps which currently lead down to the lowest level of the chamber with a ramp. This would open up an additional whole level for wheelchair users.
14	Steps and Stairs	Install clear directional signage on all stairs leading to final exit points
15	Disabled WC Facilities	The handrail supports were found to be high for wheelchair use and offered little area of grip. Consider replacing the left hand descending handrail with a compliant oval or round design and at a height of no greater than 750mm from the floor. It would not be seen as reasonable to replace the existing right hand side descending rail.
16	Corridors and Passageways - 1st floor Bloc J	Install a handrail to the left side descending at a height of 750mm and of a round or oval design to offer assistance to wheelchair users and those unsteady on their feet.

Lolfa'r Aelodau	Ymchwilio i'r posibilrwydd o osod un ai lifft llwyfan neu lift fertigol i gadeiriau olwyn gyda chymorth cwmni lifftiau cymwys y Ddeddf Cydraddoldeb. Byddai ail ddynodi'r Lolfa Aelodau ar y llawr cyntaf yn brif lolfa hefyd yn opsiwn.	17	Members Lounge	Investigate the viability of installing either a wheelchair platform lift or a vertical wheelchair lift with the assistance of a competent Equality Act compliant lifting company. Sdesignating the Lounge on the first floor would also be an option.
Diangfeydd	Cynllun cyfeillio, byddai'n ddoeth profi adeg ymarferion tân pa mor effeithiol yw system fel hyn.	18	Means of Escape	Buddy system, the effectiveness of this system would be advised to be tested within regular fire drills.
Coridor llawr cyntaf bloc B	Edrych i ledu agoriad rhai o'r drysau dwbl yn y coridor.	19	First floor coridor, bloc B	Look at widening the opening of some the double doors in the corridor